Originating Office:
AIR-130Document Description:
AC 20-182AProject Lead/Reviewer
Lee NguyenReviewing Office:
April 2016Date of Review:
April 2016

	Commenter Name	Section # and Page #	Comment	Suggested Change and Rationale	Disposition
1.	Vonnie Tong (ANM-130L)	Section 1.1, page 1 (the last two sentences)	The guidance is applicable for part 23, 25, 27, and 29 aircraft. But "For forward-looking windshear and/or turbulence detection capability, the guidance in this AC applies to fixed-wing airplane installations". A clarification may be needed for consistency for these two paragraphs.	This guidance generally is applicable for part 23, 25, 27, and 29. But for Equipment Class A (forward-looking windshear detection) and Class B (forward-looking turbulence detection) (referring to the TSO-C63e), the guidance only applies to fixed-wing airplane installation.	Accepted. This AC addresses installation guidance, not equipment minimum performance associated with the equipment classes defined in TSO-C63e. Clarified last sentence of paragraph 1.1 as follows: For forward-looking windshear and/or turbulence detection capability, the guidance in this AC applies to parts 25 and 23 fixed-wing airplane installations.
2.	Vonnie Tong (ANM-130L)	Section 5.7, page 3	This paragraph identifies if the radar system has the downlink capability but did not identify what type of radar data will be transmitted. Since there is the requirement to "ensure" the system of transmitting the radar data as specified, it would be difficult for the ensuring process/procedure if we don't specify the radar data.	Define the downlink "raw" radar data type to be transmitted from TBD source to TBD destination via TBD protocol.	Partially accepted. The intent of paragraph 5.7 is to provide general guidance that if the radar system includes downlink capability, then follow the manufacturer's recommended instructions, e.g. installed/wired per the

Originating Office:
AIR-130Document Description:
AC 20-182AProject Lead/Reviewer
Lee NguyenReviewing Office:
April 2016Date of Review:
April 2016

	Commenter Name	Section # and Page #	Comment	Suggested Change and Rationale	Disposition
					installation instructions, to ensure that the system is capable of transmitting the radar data as specified by the manufacturer. This AC does not address data link transactions and message protocol. Clarified paragraph 5.7 as follows: "If the radar system includes downlink capability, follow the radar manufacturer's recommended procedures to ensure the system is capable of transmitting the radar data as specified by the manufacturer."
3.	Vonnie Tong (ANM-130L)	Section 6.1.3, page 4	Typo: Paragraph 5.b (2) does not exist in the AC. Correct the following statement "visual and aural alerts as specified in paragraph 5.b (2) of this AC."	Change 5.b (2) to 6.2.1 (confirm if appropriate reference).	Accepted. Corrected paragraph 6.1.3 as follows: "When the forward-looking windshear function is enabled,

Originating Office:
AIR-130Document Description:
AC 20-182AProject Lead/Reviewer
Lee NguyenReviewing Office:
April 2016Date of Review:
April 2016

Commenter Name	Section # and Page #	Comment	Suggested Change and Rationale	Disposition
				you must ensure the system will automatically activate without flight crew intervention during descent to approach at an altitude sufficient to allow visual and aural alerts as specified in paragraph 6.2.2 of this AC."

Originating Office:	Document Description :	Project Lead/Reviewer	Reviewing Office:	Date of Review:
AIR-130	AC 20-182A	Lee Nguyen		April 2016

		1			<u>, </u>
1.	Bob Stoney	Section 10,	<u>BACKGROUND</u>	Delete paragraph 10.7	Accepted.
	(ANM-160S)	page 9	Applicants sometimes confuse a "system	and renumber.	
		(AFM/S),	limitation" with information appropriate in the		Changed as suggested.
		paragraphs	certificate limitations section of the R/AFM/S.	Change paragraph 10.2	
		10.2 and	The AFM limitations section is for listing	to read: "Provide	
		10.7	limits necessary to promote safe conduct of	limitations that are	
			flight (ref: 2X.1581). The limitations section	necessary for the safe	
			should <i>not</i> be used to list system "drawbacks,"	operation of the weather	
			constraints, or design features, or to describe a	radar system."	
			lack of capability. Additionally, the	-	
			limitations section should not be used as a		
			place to simply highlight <i>important</i>		
			information that is otherwise not limiting in		
			nature.		
			Applicants sometimes do not understand this		
			distinction and put information in the		
			limitations section that:		
			1. May be unclear		
			2. Is not directive in nature, and may be		
			misinterpreted		
			3. Can detract from the overall usefulness of		
			the limitations section by "watering down"		
			true limitations. Extraneous and unnecessary		
			information in the limitations section should be		
			avoided.		
			uvoided.		

Originating Office:	Document Description:	Project Lead/Reviewer	Reviewing Office:	Date of Review:
AIR-130	AC 20-182A	Lee Nguyen	_	April 2016

5.	Ray Mei (ANM-130S)	Section 6.2.1 page 4 Section 7.1	"the latest revision of the following ACs for parts 23, 25, 27, and 29 aircraft." Forward-looking wind shear only applies to fixed wings. The term "airplane" is located in 3 places.	Delete parts 27 and 29. Change "airplane" to	Accepted. Changed as suggested. Accepted.
	Thompson (ANM-130S)	page 6		"aircraft" to be more consistent and match TSO-C63d and TSO-C63e.	Changed as suggested.
6.	Ray Mei (ANM-130S)	Section 9.2, page 7	"as described in paragraphs 8 and 8.a. of this AC" There is no section 8.a in this AC.	Correct the typo.	Accepted. Corrected last sentence of paragraph 9.2 as follows: "Installation testing of the forward-looking windshear function often relies on general weather radar functional testing as described in paragraphs 9, 9.1.1 and 9.1.2 of this AC and integration testing versus dedicated forward-looking windshear flight testing."
7.	Ray Mei (ANM-130S)	Section 9.3, page 8	"as described in paragraphs 8 and 8.a. of this AC" There is no section 8.a in this AC.	Correct the typo.	Accepted. Corrected third sentence of paragraph 9.3 as follows: "Installation testing of these functions often relies on general

Origina AIR-130	ting Office:)	Document Desc AC 20-182A	ription:	Project Lead/Reviewer Lee Nguyen	wer Reviewing Office:		Date of Review: April 2016
						described in pa	functional testing as ragraphs 9.1.1 and and integration ledicated flight
8.	ACE-114 D. Jenson	6.1.3, pg 4	Reference 5.b(2) does not look correct	t Correct reference necessary	e as	must ensure the automatically a crew interventi approach at an allow visual an	vard-looking tion is enabled, you
9.	ACE-111 J. Brady	9.2.1 pg 7/8	Minor comment: "Flying in or near stocan be extremely hazardous. Flight creshould exercise good judgment for safe based on knowledge of their own ability of the capability of the aircraft when considering approaching or penetrating storm cell or turbulent area." This statement, although true, has not do with "Airworthiness Approval for a	removed from the Airworthiness A AC. g any ning to	ne	follows: "Note: Flying cells can be extended from the crews shaded from the crew shaded	in or near storm remely hazardous. ould exercise good afe flight based on

Originating Office: AIR-130	Document Description : AC 20-182A	l . <i>"</i>	Reviewing Office:	Date of Review: April 2016
AIK-130	AC 20-182A	Lee Nguyen		April 2016

			Weather Radar Systems." It is an operational statement and not an airworthiness approval requirement.		knowledge of their own abilities and of the capability of the aircraft when considering approaching or penetrating any storm cell or turbulent area."
10.	ASW-140 Jonathan Kim	4.1 & 4.2 Page 2	Both paragraphs are calling out TSO-C63e	FAA published TSO-C63d and not TSO-C63e. The AC should only specify what is on the latest TSO version.	Not accepted. This draft AC references the draft TSO-C63e, <i>Airborne Weather Radar Equipment</i> . It is planned to issue the draft AC and TSO at the same time.
11.	ASW-140 Jonathan Kim	6.1.3 Page 4	" specified in paragraph 5.b (2) of this AC."	There is no paragraph 5.b (2). Please correct paragraph reference.	Accepted. See disposition to comment 3.